
HURRICANE PROTECTION PROJECT

数100mm (数5000 电温度 application)。

FOX POINT HURRICANE BARRIER

PROVIDENCE RIVER, PROVIDENCE, RHODE ISLAND

DESIGN MEMORANDUM NO. 14 CONCRETE AGGREGATES



U.S. Army Engineer Division, New England Corps of Engineers Waltham, Mass.

NOVEMBER 1959

ENGWE(3 Nov 59)

lst Ind

SUBJECT: Design Memorandum No. 14, Concrete Materials, for Fox Point Hurricane Barrier, Providence, Rhode Island

Office of the Chief of Engineers, Washington, D.C., 27 November 1958

TO: Division Engineer, U.S. Army Engineer Division, New England, Waltham, Mass. ATTN: NEDGW

Approved.

FOR THE CHIEF OF ENGINEERS:

1 Incl w/d

F. B. SIJCHTER

Chief, Engineering Division

Civil Works

U. S. ARMY ENGINEER DIVISION, NEW ENGLAND

CORPS OF ENGINEERS

424 TRAPELO ROAD WALTHAM 54. MASS.

ADDRESS REPLY TO: DIVISION ENGINEER

REFER TO FILE NO. NEDGW

3 November 1959

SUBJECT: Design Memorandum No. 14, Concrete Materials, for

Fox Point Hurricane Barrier, Providence, Rhode Island

TOs

Chief of Engineers
Department of the Army
Washington, D. C.
ATTENTION: ENGWE

In accordance with EM 1110-2-1150 there is submitted for review and approval 10 copies of the Design Memorandum No. 14, Concrete Materials, for the Fox Point Hurricane Barrier, Providence, Rhode Island.

FOR THE DIVISION ENGINEER:

JOHN WM. LESLIE

Chief, Engineering Division

Incl (10 cys)
Des Memo No. 14,
Concrete Materials Fox Point

FOX POINT HURRICANE BARRIER PROVIDENCE RHODE ISLAND

DESIGN MEMO NO. 14

CONCRETE MATERIALS

INDEX TO DESIGN MEMORANDA

| No. | Title | Submission Date | Approved |
|-----|-----------------------------------|-----------------|-------------|
| 1 | Geology | .9 Oct 1959 | |
| 2: | Hydrology Preliminary Final | 3 June 1959 | 8 June 1959 |
| 3 | Deleted | | |
| 4 | Hurricane Tidal Hydraulics | | |
| 5 | General Design Memo | | |
| 6 | Embankment & Foundations | | |
| 7 | Structural Section I | | |
| 8 | Structural Section II | | |
| 9 | River Gates | | |
| 10 | Pumping Station | | |
| 11 | Cooling Water Canal | | |
| 12 | Sewer & Utility Modifications | | |
| 13 | Providence River Studies | | |
| 14 | Concrete Materials | · | |

FOX POINT HURRICANE BARRIER

DESIGN MEMORANDUM NO. 14

CONCRETE MATERIALS

CONTENTS

| Paragraph | Subject | Page |
|------------------|---|-------------------|
| | A. AGGREGATES | 1 |
| 1 2 3 4 | General Investigations Tests Relative Cost Estimates a. Romano Sand and Gravel Company b. Morse Sand and Gravel Company c. Fanning and Doorley Construction Company d. New Haven Trap Rock Company e. M. A. Gammino Company | 1 1 1 2 2 2 2 2 2 |
| | B. WATER | 2 |
| 5 6 | General Tests | 2 3 |
| | C. FOUNDATION SOILS | 3 |
| | D. CONCLUSIONS AND RECOMMENDATIONS | 4 |

LIST OF PLATES

| Plate No. | <u>Title</u> |
|-----------|--|
| 14~1 | Location of Commercial Aggregate Sources |
| 14-2 | Romano Company Water-Cement Ratio |
| 14-3 | Morse Sand and Gravel Company, Water-Cement Ratio |
| | LIST OF TABLES |
| No. | <u>Title</u> |
| 14-1 | Concrete Aggregate Investigations Test Data Summary |
| 14-2 | Concrete Aggregate Investigations Test Data Summary |

U. S. ARMY ENGINEER DIVISION, NEW ENGLAND CORPS OF ENGINEERS 424 TRAPELO ROAD WALTHAM 54, MASSACHUSETTS

FOX POINT HURRICANE BARRIER

PROVIDENCE RIVER

RHODE ISLAND

DESIGN MEMORANDUM NO. 14

CONCRETE MATERIALS

OCTOBER 1959

A. AGGREGATES


- 1. General. Approximately 55,000 cubic yards of concrete will be required for construction of the barrier, pumping station, and floodwalls of the Providence Hurricane Protection Project. In view of the relatively small quantity of aggregates and the absence of undeveloped sources on the site, investigations have been confined to established commercial sources. All of the three commercial sources within a 15-mile radius of the project site have been recently investigated and tested. A fourth commercial source, although at a distance of 100 miles, is considered because of its high quality aggregate and economic availability. A fifth commercial source, which was only recently developed, is presently being investigated and tested, and the results will be issued as an addendum to this design memorandum. Locations of these sources are shown on Plate No. XIV-1.
- 2. Investigations. Selection of the sources for testing was based on plant facilities and characteristics of materials as determined by visual examination. All of the natural sand and gravel sources investigated are developed in Pleistocene glacial outwash deposits and exhibit a lithological similarity. The Fanning and Doorley Quarry (crushed stone) is developed in igneous rock of the Devonian age. The New Haven Trap Rock Quarry is developed in igneous rock of the Triassic age.
- 3. Tests. Representative samples of the aggregates have been tested for evaluation. Results of the aggregate tests are summarized in Tables XIV-1 and XIV-2.
- 4. Relative Cost Estimates. Estimated delivered prices of the aggregates, based on quoted plant prices, Rhode Island Department of Public Utilities minimum trucking rates, which are currently 25 cents

per ton for the first mile and 5 cents per ton for each additional mile, and current railway shipping charges, are as follows:

- a. Romano Sand and Gravel Company. The nearest commercial source is the Romano Sand and Gravel Company with its main processing plant located at East Providence, Rhode Island, about 4 miles haul distance from the project site. Plant prices are \$1.35/ton for gravel and \$0.75/ton for sand. The delivered price to the site will average \$1.75/ton for gravel and \$1.15/ton for sand.
- b. Morse Sand and Gravel Company. The Morse Sand and Gravel Company, with its main processing plant located in Dodgeville, Massachusetts, about 10 miles haul distance from the project site. Plant prices are \$1.35/ton for gravel and \$1.00/ton for sand. The delivered price to the site will average \$2.05/ton for gravel and \$1.70/ton for sand.
- c. Fanning and Doorley Construction Company. The Fanning and Doorley Construction Company has its main quarry located at Ashton, Rhode Island, about 12-mile haul distance from the project site. Plant prices for crushed stone range from \$2.15/ton to \$2.55/ton. The delivered price to the site will average \$3.15/ton.
- d. New Haven Trap Rock Company. The New Haven Trap Rock Company has its main quarry located at North Bradford, Connecticut, about 100 miles rail distance from the project site. Plant prices for crushed stone average \$1.40/ton. The delivered price to the site will average \$2.25/ton.
- e. M. A. Gammino Company. The M. A. Gammino Company has its quarry and processing plant located at Cranston, Rhode Island, about 6 miles haul distance from the project. *Plant prices for crushed stone average \$1.80/ton. The delivered price to the site will average \$2.30/ton.*
- *f. Rhode Island Sand and Gravel Company. The Rhode Island Sand and Gravel Company, with its main processing plant located in Warwick, Rhode Island, about 7 miles haul distance from the project site. Plant prices for concrete sand are \$1.05/ton. The delivered price to the site will average \$1.55/ton.*

B. WATER

5. General. The concrete in this waterfront structure will be subjected to the contaminated water in the Providence River, which is a tidal estuary. Therefore, it was deemed necessary to investigate this water so that the necessary protection can be provided. A comprehensive sampling and testing program has been conducted by Bureau of Public Health in connection with other phases of the design studies. In addition, a separate detailed sampling and testing program has been conducted in connection with an investigation of corrosion properties of the water and river mud. Samples were obtained at the high, low, and mean tides, three feet from the water surface and three feet from the bottom and at various other elevations.



M. A. GAMMINO COMPANY, COARSE AGGREGATE RHODE ISLAND SAND AND GRAVEL COMPANY, FINE AGGREGATE

FOX POINT BARRIER PROVIDENCE, RHODE ISLAND

| BER | | | | AILES | MATERIAL | SIZE | TESTING | MOER | | | | | VE ANALI CENT PAS | SSING | of aggre - by we | | | | | | SS US IN TEST | LOSS TEST | LOSS | H MOR | TAR ST ERCENT STAND | RENGT OF ARD | FLAT | WEIGHT | 11TY 10US | NOL | G | PECIFIC RAVITY | | · | | | sive st | | · · · · · · · · · · · · · · · · · · · | | ringat. | PANSION | DURABILITY FACTOR (DFE) 300 CYCLES |
|------|---------------------------|---------------------------------|---|-------|------------------------------|------------------------------|----------------------|--------------------------------------|-----|----------------|---------|---------------|----------------------|-------|---------------------|-------|---------|--------|-------|----------|------------------------------------|----------------------|------------|----------|---------------------------|--------------------|------|-------------------|-----------------------|--------------------------|------------------------------|--------------------------------------|----------------------------------|--------|------------|---|----------|--------|---------------------------------------|------|---------|--|--|
| \ \S | | OURCE AND | REMARKS AND | Z | TESTED | ال ال | LABORATORY AND | 2 2 | | SIEVE S | SIZE IN | INCHES | | | U.S. S | TANDA | RD SIEV | /ES NU | MBERS | S | ASIO | ESS - | , ¥ ₹ | X | , | 28 | S 2 | 2 A A | REACTIVE DELETERIC | ABSORPT | ¥ | ¥ € | ERT | | AVERAG | | | | | | | | ABIL CAC |
| E Z | LO | CATION | SOURCE | 1 | (PROCESSED) | 75 E | DATE OF TESTS | P. | 2 ½ | 2 1 | . . | 3 4 | 1 | 3 8 | 4 8 | 16 | 30 | 50 | 100 | 200 | ABR ABR | RCE SON SLE | PERCEN | E S DAY | DAY | 28 DAY | E | PERCEN | AEA ELE | ABS(| BULK | BULK S. DR | ⋖ . | | T FACTO | | <u> </u> | | | | | X X | 85°8 |
| = | | | | Ŧ | | ž | | SAR | -2 | - '2 | ' | 4 | 2 | 8 | | | | " | | | ₹8 | SOUNDNES S CYCLES | ORO B S | ₹ | | | PAF | 9 83 | _ 6 | | | S | АРР | 5.0 6 | »0 7° | ,0 5. | •0 6. | ,0 7. | 0 5.0 | 6.0 | 7.0 | E | |
| 1 | M.A. Ga Granst | mmine Co. | Operating Quarry | 6 | Crushed Diorite Gmeiss | 2" 1 1/2" 3/4" 1/2" | NED December 1960 | 61-6-1 61-6-2 61-6-3 61-6-4 | - | 84 27 - 100 | 100 | 10 89 - | 1 29 100 9 | - | - 1 26 4 | - | - | - | | ** ** | 8.32 7.28 6.87 28 5.78 | 3. | .0 | | | | | 3.5 8.9 8.4 | nnoc None | 0.4 0.6 0.8 1.4 | 2.82 2.77 2.78 2.73 | 2.83 2 2.79 2 2.80 2 2.77 2 | 2. 85 2. 82 2. 85 2. 84 | 2hho 3 | n60 1,26 | io 319 | 90 40: | 30 503 | 90 1110 | 4860 | | *2* | 66* |
| \$ | Rhode Sand & Warwic | Island Gravel Co. k, R.I. | Operating Fit in glacial outwash deposits | 7 | Natural Sand | No• It | | 61-5-1 | - | - | - | - | • | - | 100 88 | 66 | 43 | 13 | 3 | 1.2 | 2.87 - | 5. | .9 .50 | .00 | 121 | 139 | | I | nnoc None | 0.7 | 2.62 | 2,63 2 | 2.66 | · | | - In the second | | | | | | The state of the s | inasionasaina irancin |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

PETROGRAPHIC ANALYSIS

1. Predominately Quarts Gneiss, Schist, Vein Quartz and Pegmatite. 79% Diorite Gneiss, 16% Schist, 5% Vern Quartz and Pegmatite, 10% moderately weathered.

2. 'Is composed 73% Quartz and Quartzite, 19% Granite and Pegmatite, h% Gneiss, 2% Schist, and 2% Basic Rock Types, 1% moderately weathered.

* Tested February 1960 by SAD Laboratories

PROVIDENCE LOCAL PROTECTION
FOX POINT BARRIER
PROVIDENCE R. I.

CONCRETE AGGREGATE INVESTIGATION TEST DATA SUMMARY

NEW ENGLAND DIVISION LABORATORIES CORPS OF ENGINEERS NEW ENGLAND DIVISION WALTHAM, MASS. DECEMBER 1960 per ton for the first mile and 5 cents per ton for each additional mile, and current railway shipping charges, are as follows:

- a. Romano Sand and Gravel Company. The nearest commercial source is the Romano Sand and Gravel Company with its main processing plant located at East Providence, Rhode Island, about 4 miles haul distance from the project site. Plant prices are \$1.35/ton for gravel and \$0.75/ton for sand. The delivered price to the site will average \$1.75/ton for gravel and \$1.15/ton for sand.
- b. Morse Sand and Gravel Company. The Morse Sand and Gravel Company, with its main processing plant located in Dodgeville, Massachusetts, about 10 miles haul distance from the project site. Plant prices are \$1.35/ton for gravel and \$1.00/ton for sand. The delivered price to the site will average \$2.05/ton for gravel and \$1.70/ton for sand.
- c. Fanning and Doorley Construction Company. The Fanning and Doorley Construction Company has its main quarry located at Ashton, Rhode Island, about 12-mile haul distance from the project site. Plant prices for crushed stone range from \$2.15/ton to \$2.55/ton. The delivered price to the site will average \$3.15/ton.
- d. New Haven Trap Rock Company. The New Haven Trap Rock Company has its main quarry located at North Bradford, Connecticut, about 100 miles rail haul distance from the project site. Plant prices for crushed stone average \$1.40/ton. The delivered price to the site will average \$2.25/ton.
- e. M. A. Gammino Company. The M. A. Gammino Company has its quarry and processing plant located at Cranston, Rhode Island, about 7 miles haul distance from the project. This source will be in economic competition with the other sources.

B. WATER

5. General. The concrete in this waterfront structure will be subjected to the contaminated water in the Providence River, which is a tidal estuary. Therefore, it was deemed necessary to investigate this water so that the necessary protection can be provided. A comprehensive sampling and testing program has been conducted by Bureau of Public Health in connection with other phases of the design studies. In addition, a separate detailed sampling and testing program has been conducted in connection with an investigation of corrosion properties of the water and river mud. Samples were obtained at the high, low, and mean tides, three feet from the water surface and three feet from the bottom and at various other elevations.

6. Tests. Typical results of laboratory tests performed on the samples of river water taken three feet from the top and bottom are as follows:

| | | Test Resu | ılts (Parts | s per Mil | lion) (1) | |
|---|-----------------|----------------|-----------------|-----------|----------------|--------|
| | Low | Tide | Me ar | n Tide | High | Tide |
| Tests | Top | Bottom | Top | Bottom | Top | Bottom |
| ${\mathbb H}_{\mathbf C}$ | 7.4 | 7.4 | 7.9 | 7.3 | 8,3 | 7.6 |
| Turbidity | 7†0 | . :3 | 50 | .2 | 70 | 8 |
| Free Carbon | 11.5 | 14.3 | 2.0 | 12.0 | 0.0 | 6.5 |
| Dioxide | | | | | | , |
| Alkalinity (as CaC | 10,) | | | | | |
| Total | 98 | 100 | 96 | 105 | 97 | 103 |
| Carbonate | 0 | 0 | Ō | 0 | 23 | 0 |
| Bicarbonate | 98 | 100 | 96 | 105 | 74 | 103 |
| Hydroxide | 0 | 0 | 0 | 0 | 0 | 0 |
| Free Mineral Acid | 0 | 0 | 0 | 0 | 0 | 0 |
| Total Hardness (as C _a CO ₃) | 000و لم | 5 , 250 | 200و با | 5,550 | 4,600 | 000و 5 |
| Ferrous Iron, Tota | al O | 0 | 0 | 0 | 0 | 0 |
| Ferric Iron Total | بليل. ٥ | 0.28 | 0•ftft | 0.20 | 0•40 | 0.30 |
| Dissolved | 0.02 | 0.02 | 0.02 | 0.02 | 0.04 | 0.02 |
| Suspended | 0.42 | 0.26 | 0.42 | 0.18 | 0,36 | 0.28 |
| Sulfides as S= | 0.05 | 0.05 | 0.05 | 0.05 | 0.05 | 0.05 |
| Silica | 2.2 | 3.2 | 1.0 | 1.6 | 1.0 | 0.04 |
| Sulphates | 750, | 2 ,31 0 | 1,880 | | 1 , 980 | 2,230 |
| Chlorides | 750, | 16,870 | 13 , 650 | 16,890 | 500و بلا | 16,150 |
| Manganese | 0 | 0 | 0 | 0 | 0 | 0 |
| Solids, Total | 23 , 520 | 31,200 | 25 , 370 | 32,650 | 27,980 | 31,720 |
| Staining | Severe | Severe | Severe | Severe | Severe | Severe |

(1) Except for pH.

C. FOUNDATION SOILS


The foundation materials consist of organic silts in the river, and fill material on the abutments which consist in part of unburned coal and coal ashes. The bedrock contains the Rhode Island Series which is, in part, carboniferous. Tests on the mud indicate a sulfide content in excess of 2,000 p.p.m. Based on these data, it is considered that potentially reactive material is present in the foundation soils.

D. CONCLUSIONS AND RECOMMENDATIONS

Based on the data presented herein, the durability of the crushed quarry stone coarse aggregates is substantially greater than for the gravel coarse aggregate. However, all of the aggregates tested are considered acceptable for use in the proposed structure and approval of these sources is recommended.

Tests performed on the river water show that the sulfate content exceeds the maximum limit (1000 ppm) permitted by Civil Works Bulletin ENGWE 56-18 for Type II cement. Therefore, in accordance with this bulletin, Type V cement is required for the exposed portions of the structure. However, due to the relatively small quantity of concrete required and difficulty in handling two types of cement, it is recommended that Type V cement be used throughout. This would include use in any concrete piles because of the potential reactivity of the foundation soils.

No consideration is given to use of the river water for either mixing or curing concrete. Water for these uses will be obtained from the City water supply or other acceptable source.




- Fox Point Barrier
- (2) L. Romano Sand & Gravel Co.
- Morse Sand & Gravel Co.
- New Haven Traprock Co.
- (5) M. A. Gammino Co.
- 6 Fanning & Doorley

PROVIDENCE LOCAL PROTECTION
FOX POINT BARRIER
PROVIDENCE, R.I.


LOCATION OF COMMERCIAL AGGREGATE SOURCES

NEW ENGLAND DIVISION LABORATORIES
CORPS OF ENGINEERS NEW ENGLAND DIVISION
WALTHAM, MASS. OCT. 1959



ROMANO SAND AND GRAVEL CO., AGGREGATES

FOX POINT BARRIER
PROVIDENCE, RHODE ISLAND



MORSE SAND AND GRAVEL CO., AGGREGATES

FOX POINT BARRIER PROVIDENCE, RHODE ISLAND

| 3ER | | | ES | | 2E | T-07440 | BER | | | | | Sieve A | Analys | sis o | f Agg | regai Weig | te ht | · · · · · · | | | | | TEST TIONS OSS | TEST Ag SO, | MTIES TE I | MORT/ PE | AR STE RCENT TANDA | RENGT OF IRD | FLAT | ED | | Ls & | NO F | SPEC GRAV | | | | | | | ve Stre | | | | FICENT SASSON F | ITY OFE) |
|--------|--|---|----------|--------------------|--|------------------------|--|-------|-------|------|-------------|------------------------|--------|------------------|-------------------|-------------------|-------------|-------------|---------|------------------|-----|------------------------------|---------------------------------------|----------------|---|-------------|--------------------------|--------------------|--------|---------|------|------|---------------------------------|--|---------------------------------------|----------|-------|-------|----------------|--------|---------|------|----------|------|-----------------------|--|
| NUMB | SOURCE | REMARKS And | <u> </u> | MATERIAL TESTED | L SI | TESTING LABORATORY | 2 | | SIEVE | SIZE | | | | | | | | D SIEV | ES NI | MBER | s | 10. US | SION OLUTI | SS | 7 2 2 Z | | | | N ES | SAT S | | ERIA | RCEN | ایرا پ | Z Z | <u> </u> | | | | | | | 28 DAY A | | S Z | 1 2 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 |
| ITEM N | LOCATION | SOURCE | | (PROCESSED) | NORMA | AND DATE OF TESTS | SAMPLE | 2 1/2 | 2 | 1 2 | | 3 | d i | 3 . ■ | 4 | 8 | 16 | 30 | 50 | 100 | 200 | FINE | L.A. ABRASIO 500 REVOLU PERCENT | SCYCLE | PERCENT ORGANIC INF (PPW ASTM PL | DAY | DAY | DAY | PARTIC | PERCENT | REA | MAT | ABSC | BULK | S S S S S S S S S S S S S S S S S S S | 5. 0 | | | | . 0 6. | | | 5.0 6.0 | | LINE AL THE FRAAA | DURABILITY FACTOR (DFE) 300 CYCLES |
| 1. | Romano Sand & Gravel Co. E. Providence, R. I. | Operating pit in glacial outwash deposits | | Gravel | 2-1/2" 1-1/2" 3/4" 3/8" | S. A. D. March 1959 | 82-579 82-578 82-577 82-576 | | 100 | 100 | ' - | 91 2 | | - 2 | - - 1 16 | - - - 11 | , , , , , , | | . 1 1 2 | - - - - | - | 7.90 7.83 7.06 5.79 | 24 | | | | | | | 7 I | nnoc | None | 0.8 0.8 0.7 1.2 | 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2 | 68 | 176 | 8 259 | 98 26 | 59 24 ! | 51 35 | 05 374 | 45 3 | 225 383 | 4224 | 6.2 | 54 |
| 2. | | · | - | Natural Sand | | | 82-575 | - | - | - | - | | - | \dashv | | 83 | 58 | 37 | 18 | 6 | 2. | 2. 98 | · <u>-</u> | 15.2 | 2 < 500 | | | 104 | (| 9 1 | nnoc | None | 1.2 | 2. | 66 | | | | | | | | | | 5 , 4 . | |
| 3. | Morse Sand & Gravel Co. Dodgeville, Mass | Operating pit in glacial outwash deposits | | | 2-1/2" 1-1/2" 1" 3/4" 3/8" | S. A. D. March 1959 | 82-574 82-573 82-572 82-571 82-570 | - | - | | | 1 43 64 100 8 | | - 2 1 3 | - - 9 13 | - - 4 3 | 1 1 1 | | - | - | - | | 17 | 2.8 | 3 | | | | 8 | 3 1: | nnoc | None | 0.6 0.7 0.6 1.1 1.4 | 2. 6 2. 6 2. 6 2. 6 2. 6 | 58 57 56 | 2650 | 335 | | | | | | 3915 435 | | 5.2 | . 46 |
| 4. | = | |] | Natural Sand | No. 4 | | 82-569 | 1 | - | - | - | - | - 1 | .00 | 99 | 83 | 54 | 26 | 10 | 4 | 2 | 3, 24 | - | 8.4 | 4 < 500 | | | 117 | 10 |) I | nnoc | None | 1.1 | 2. | 65 | | | | | | | | | | 5 | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | - | | | | | | | | | | | |

Petrographic Analysis

1. Gravel: Predominantly Quartzite, Granite, and basic igneous rocks, with slate & phyllite and miscellaneous rock types. 36% Quartzite, 19% Granitic Rock Types, 19% Basic Rock Types, 13% Slate & Phyllite, 7% Conglomerate, 4% Veinqartz, 2% Miscellaneous, 18% weathered.

2. Sand: Is composed of 66% Quartz and Quartzite, 7% Granitic Rock Types, 9% Basic Rock Types, 9% Slate & Phyllite, 4% Feldspar, 5% Miscellaneous.

3. Gravel: Predominantly Granitic Rock Types, Quartzite and basic igneous rocks, and miscellaneous rock types. 31% Granitic Rock Types, 20% Basic Rock Types, 17% Slates, Phyllite, and Schist, 20% Quartzite, 9% Conglomerate, 3% Miscellaneous, 9% Moderately weathered.

4. Sand: Is composed 58% Quartz & Quartzite, 11% Granitic Rock Types, 9% Basic Rock Types, 8% Slate, Phyllite & Schist, 8% Feldspar, 5% Miscellaneous.

* Compressive Strength Tests by NED Laboratory

PROVIDENCE LOCAL PROTECTION
FOX POINT BARRIER
PROVIDENCE R.I.

CONCRETE AGGREGATE INVESTIGATIONS TEST DATA SUMMARY

NEW ENGLAND DIVISION LABORATORIES CORPS OF ENGINEERS NEW ENGLAND DIVISION WALTHAM, MASS. OCT 1959

| gr. | | | ES | | SIZE | | BER | | | Siev | ve Anal | ysis of | Aggre | gate | | | | | S # TEST FIONS | TEST AgSO ₄ OSS | RITES IOM I | RTAR S PERCEN STAND | TRENGT T OF ARD | FLAT | WEIGHT | Sno Sno | NO. | SPE (| | | | | npressive S | | | | FICIENT | PENSICA PE | DURABILITY FACTOR (DFE) 300 CYCLES |
|-----|--|-------------------|---|--------------------|--|--|---------|--------|----------|-----------|--------------------------------|---------|-------------------|-------|-------------------|-------|-----------------|-------------|--|----------------------------------|-------------------|---------------------------|-----------------------|----------------------------|--------|------------|-------------|-------|-----------|----------|--------|------|-------------|--------|--------------|---------|---------------|----------------|--|
| MBE | SOURCE | REMARKS | X | MATERIAL | S | TESTING LABORATORY | NO N | S | HEVE SIZ | | | | | | ARD SIE | VES N | UMBERS . | Z 12 | U LU | SS - N | MPU PLA PLA | | | ES IND IGAT | KAL | TERI | RPT | | RY FNT | <u> </u> | | | 14 DAY AV | | | | 0 " | χ ₀ | 120 28 8 20 |
| ž | AND LOCATION | AND SOURCE | <u>ر</u> | (PROCESSED) | SM AL | AND DATE OF TESTS | PLE | | | | 3 1 | 3 | | | . 70 | 50 | 100 20 | FINE | MOD MOD | NONE CLES | STM P | S 7 | 28 Y DAY | PARTICI FLON | AL AL | DELE | ABSO PEF | BULL | | CEME | ENT FA | CTOR | CEMENT F | ACTOR | CEME | NT FACT | OR N | X | 8 C T S |
| ΞE | | | HAU | | Š | , | SAM | 2 2 2 | 12 | 1 | 3 1 | 3 8 | 4 | 8 1 | 6 30 | 50 | 100 20 | | 188 98. | SOUNDNES 5 CYCLES PERCEN | ORG AS | | | PAR | PERCEN | | 1 | | SS | 5.5 | 6.0 | 6.5 | 5.5 6.0 | 6.5 | 5.5 | 6.0 | 6.5 SE | | -6" |
| 5 | Fanning & Doorley Quarr Ashton, Rhode Island | Operating Quarr | у 12 | Crushed Granite | 2-1/2' 1-1/2' 3/4'' 1/2'' 3/8'' | S. A. D. April 1956 Tested for Woon- socket Local Protection Project | 82-228 | | 100 | 100 9 | 23 4 95 8 00 88 - 100 | | - - 1 24 | - | | 1 | | 7 7 6 | . 54 . 74 | 0.9 | | | | 11 11 13 22 13 | Inno | c None | 0.4 0.2 | 2. | .67 | | | | | | | | 4. | . 3 | 79 |
| .6 | New Haven Trap Rock Co. North Bradford, Conn. | p Operating Quarr | у 101 | Crushed Diabase | 2" 1" 3/4" 1/2" 3/8" | O. R. D. February 1955 Tested for Bosto Army Base | n 55228 | 100 99 | 100 | 71 100 | 27 1 99 29 - 100 | 38 | - 2 2 77 | | 10 10 | | 8 - | 7 6 6 | 5.57 2.73 3.96 13.5 5.60 2.74 | | | | | 7 .16 | Inno | oc None | 0.8 | 2. | 93 | 3710 | 4680 | 5890 | 4705 5600 |) 6880 | 4240 | 5345 65 | 580 | . 4 | 86 |
| | | | AND | | The state of the s | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

Petrographic Analysis

- 5. Granite: Predominantly quartz with some feldspar and plagioclase, mica-biotite and muscovite and miscellaneous materials. 54% quartz, 36% feldspar, orthoclase and plagioclase, 9% mica-biotite and muscovite and 1% miscellaneous materials.
- 6. Diabase: All of this sample consists of a dark-greenish-black, fine-grained, basic igneous rock with composition and texture of a diabase, 100% diabase.

Note: Durability of Fanning and Doorley Quarry crushed granite computed with fine aggregate from Wrentham Sand and Gravel Co., Wrentham, Mass., and New Haven Trap Rock diabase computed with fine aggregate from Bradford Weston, Inc., Hingham, Mass.

PROVIDENCE LOCAL PROTECTION
FOX POINT BARRIER
PROVIDENCE R.I.

CONCRETE AGGREGATE INVESTIGATIONS TEST DATA SUMMARY

NEW ENGLAND DIVISION LABORATORIES
CORPS OF ENGINEERS NEW ENGLAND DIVISION
WALTHAM, MASS. OCT 1959